

Release Notes for Conext™ RL Inverter

Release Date: 25 Jan 2017

Firmware version:

Communication firmware ("P0 SW" in the firmware upgrade tool) : V3.00.
DSP firmware ("P1 SW" in the firmware upgrade tool) : V3.13
Red firmware ("P2 SW" in the firmware upgrade tool) : V2.00.

Affected SKU Numbers:

1. PVSNVC3000S
2. PVSNVC3000
3. PVSNVC3000ST
4. PVSNVC3000T
5. PVSNVC4000S
6. PVSNVC4000
7. PVSNVC4000ST
8. PVSNVC4000T
9. PVSNVC5000S
10. PVSNVC5000
11. PVSNVC5000ST
12. PVSNVC5000T

New Features:

1. Compliance to AS/NZS 4777.2.2015 standard for Australia and New Zealand
2. New supported countries:
 - a. Brazil
 - b. Chile
 - c. Mexico